

[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [55 ELECTRICAL EQUIPMENT](#) / [5580 SPECIAL ACCESSORIES](#)
/ [5580T BOSE SOUND SYSTEM](#)
/ 5580T11 BOSE SOUND SYSTEM FRONT SPEAKER (ONE), LH OR RH - R R WITH DOOR PANEL REMOVED

2429469 - 5580T11 bose sound system front speaker (one), lh or rh - r r with door panel removed


 Removing ([Refitting](#) )

1. Disconnect the loudspeaker's electrical connection.

	Name	Connector
1	Speaker in driver's .front door	P35

	Name	Connector
1	Speaker in front passenger door	P36

2. Undo the bolts.
3. Remove the speaker.



 Refitting ([Removing](#) )

Check that the speaker is not damaged.

Position the speaker and secure it using the bolts.

Connect the electrical connection.