


[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [00 MAINTENANCE](#) / [0010 NEW UNITS AND PLANNED MAINTENANCE](#). / [0010T VEHICLE OIL AND FLUIDS](#) / 0010T64 BRAKE AND OR CLUTCH FLUID CHECK LEVEL AND TOP UP AS NECESSARY


## 2428829 - 0010T64 brake and or clutch fluid check level and top up as necessary

Check that the brake fluid in the reservoir is at the maximum level; if not, top up with the recommended fluid.

If the brake fluid level is being topped up, remove the cap and introduce fluid until the maximum level is reached.

	Type	Component	Name	Qty.
-	Synthetic fluid	BRAKE-CLUTCH HYDRAULIC SYSTEM	TUTELA TOP 4	-

The symbol on the container identifies synthetic type brake fluids as opposed to mineral type brake fluids. The use of mineral type fluids irreparably damages the special rubber seals in the hydraulic braking system.

 Take great care to avoid the brake fluid, which is highly corrosive, from coming into contact with the paintwork. If this should happen, wash immediately with water.