


[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [70 FITTINGS](#) / [7005 PASSENGER COMPARTMENT FRONT SIDE DOORS](#)
/ [7005C FRONT LOCK CONTROLS](#)
/ 7005C09 FRONT DOOR OUTER HANDLE MOUNT (1), LH OR RH - R R WITH DOOR PANEL REMOVED

2429487 - 7005C09 front door outer handle mount (1), lh or rh - r r with door panel removed


 Removing ([Refitting](#) )

- [7005D14 front side door descending window glass - r r with door panel \(and mount frame\) removed](#)
- [7005A08 interior support frame of one side door r r with door panel removed](#)
- [7005C11 front side door outside handle r r](#)

1. Loosen the outer bolt.
2. Remove the support and rod.



1. If necessary, disconnect the rod (1a) from the retainers (1b).



 Refitting ([Removing](#) )

Check that the mounting is undamaged.

Connect the rod to the retainers.

Position the support and tighten the outer bolt.

- [7005C11 front side door outside handle r r](#)
- [7005A08 interior support frame of one side door r r with door panel removed](#)
- [7005D14 front side door descending window glass - r r with door panel \(and mount frame\) removed](#)