


[LANCIA](#) / [YPSILON](#) / [1.3 JTD](#) / [PROCEDURES](#) / [70 FITTINGS](#) / [7040 BODYSHELL INTERIOR TRIMS AND FITTINGS](#)
/ [7040L CABIN FLOOR COVERING](#) / 7040L22 REAR TRIM ON TUNNEL -R.R.

2429602 - 7040L22 REAR TRIM on TUNNEL -R.R.

 Removing ([Refitting](#) )

1. Remove the trim (1a) releasig the retainers (1b).



 Refitting ([Removing](#) )

Check that the cover is undamaged.

Fit the trim and fit the retainers.